00684.109147 <u>PATENT</u>

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:	)	
	:	Examiner: M. M. Said
YASUFUMI ASAO	)	
	:	Group Art Unit: 2629
Application No.: 10/552,760	)	
	:	Confirmation No.: 2590
Filed: May 6, 2005	)	
	:	
For: COLOR DISPLAY APPARATUS	)	February 13, 2009
	:	
U.S. Patent No. 7,358,943 B2	)	
1 1 1 2 2000	:	
Issued: April 15, 2008	)	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark Office. A Certificate of Correction form is attached.

Patent No.: 7,358,943

The statutory fee of \$100.00 is being paid electronically. Any additional fee

required by this paper may be charged to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C.

office by telephone at (202) 530-1010. All correspondence should continue to be directed to our

below-listed address.

Respectfully submitted,

/Scott D. Malpede/

Scott D. Malpede Attorney for Patentee Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

SDM\rnm

FCHS\_WS 2385576v1

# Staple Here Only! SINI WILK S. HERE

# UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

**PATENT NO.** : 7,358,943 B2

**DATED** : April 15, 2008

INVENTOR(S): YASUFUMI ASAO Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 10:

Line 65, "at" should read --as--.

### COLUMN 13:

Line 31, "Suppress" should read --suppress--.

Line 39, "process-can" should read --process can--.

### COLUMN 14:

Line 17, "IN" should read --In--.

Line 28, "is" should read -- are--.

### COLUMN 19:

Line 16, "(MOdel" should read --(Model--.

### COLUMN 20:

Line 65, "made" should read --mode--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. 7,358,943 B2

No. of add'l. copies @ 30¢ per page



# Staple Here Only! WINT S.ABINIRA

# UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. 7,358,943 B2

April 15, 2008 **DATED** 

YASUFUMI ASAO Page 2 of 2 INVENTOR(S) :

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 22:

Line 43, "includes" should read --include--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

**PATENT NO. 7,358,943 B2** 

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

(Form#30)